

Legend		
Enhancement Point	Obstruction Point	Discharge Point
Existing Riparian	Beaver Dam	Agricultural Runoff
Potential Riparian	Cascade	House Effluent
Culvert	Dam	Other
Culvert	Falls	Storm Drain
Culvert with Barrier	Fences	Tile Drain
Generic Point	Log Jam	Trench
Bridge	Persistant Debris	Top of Bank
Fence	Pump	Top of Bank
Garbage/Pollution	Velocity Barrier	Segment Break
Livestock/Livestock Crossing		
Other		


City of Salmon Arm


**Sensitive Habitat Inventory Mapping
and
Wetland Inventory Mapping Project
Section Map**

Leonard Tile 1 of 3

Date: 10/17/2012
Revision Number: Final
Prepared by: ADucharme

FORSITE
 Forest Management Specialists





Legend		
Enhancement Point	Obstruction Point	Discharge Point
● Existing Riparian	● Beaver Dam	✱ Agricultural Runoff
● Potential Riparian	☞ Cascade	⊗ House Effluent
Culvert	☞ Dam	● Other
● Culvert	☞ Falls	Ⓧ Storm Drain
● Culvert with Barrier	☞ Fences	⬢ Tile Drain
Generic Point	☞ Log Jam	■ Trench
☞ Bridge	☞ Persistent Debris	Top of Bank
☞ Fence	☞ Pump	— Top of Bank
▲ Garbage/Pollution	☞ Velocity Barrier	- - - Segment Break
▲ Livestock/Livestock Crossing		
▲ Other		

City of Salmon Arm

Sensitive Habitat Inventory Mapping and Wetland Inventory Mapping Project


Section Map

Leonard Tile 2 of 3

Date: 10/17/2012
Revision Number: Final
Prepared by: ADucharme

1:3,000

Coordinate System: NAD 1983 UTM Zone 11N Transverse Mercator



Legend

<p>Enhancement Point</p> <ul style="list-style-type: none"> ● Existing Riparian ● Potential Riparian <p>Culvert</p> <ul style="list-style-type: none"> ● Culvert ● Culvert with Barrier <p>Generic Point</p> <ul style="list-style-type: none"> Bridge Fence Garbage/Pollution Livestock/Livestock Crossing Other 	<p>Obstruction Point</p> <ul style="list-style-type: none"> Beaver Dam Cascade Dam Falls Fences Log Jam Persistant Debris Pump Velocity Barrier 	<p>Discharge Point</p> <ul style="list-style-type: none"> Agricultural Runoff House Effluent Other Storm Drain Tile Drain Trench <p>Top of Bank</p> <ul style="list-style-type: none"> — Top of Bank - - - Segment Break
--	--	---

1:3,000

0 25 50 100 150 Meters

Coordinate System: NAD 1983 UTM Zone 11N Transverse Mercator

City of Salmon Arm

Sensitive Habitat Inventory Mapping and Wetland Inventory Mapping Project Section Map

Leonard Tile 3 of 3

Date: 10/17/2012
Revision Number: Final
Prepared by: ADucharme